

HEICO

LATCH ASSY, PUSH BUTTON

Turbine Kinetics Part Number: **BACL10AM090-256KT**

Boeing Service Part Number: **BACL10AM090-256**

Next Higher Assembly Part Number: 141A8701-2, -12, -13, -38, -40 - Door Assy

Eligibility:



[See FAA PMA Supplement](#)

IPC Reference:

B737-52-48

Quantity:

As Required



Location:

Door Instl-Ext Pwr Sect. 41