



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Article Name	Article Number	Approved Replacement for Article Number	Approval Basis and Approved Design Data	Make/TCH Eligibility	Model/Series Eligibility
Bolt, Machine	J644P03D QQ	J644P03D	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4 GE90-76B, GE90-77B,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					GE90-85B, GE90-90B, GE90-94B
Bolt, Machine	J644P04A QQ	J644P04A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A, -80A2, -80A1, -80A3 CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B2, -5B4, -5B5, -5B6, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B1/2P, -5B2/2P, -B3/2P, -5B4/2P, -B6/2P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P04B QQ	J644P04B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3, -80E1A2, -80E1A3, -80E1A4 GE90-76B, GE90-77B, GE90-85B,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

				CFM International	GE90-90B, GE90-94B CFM56-2, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -C2/G4, -5C3/F, -5C3/F4, -5C3/G, -C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P04D QQ	J644P04D	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-6D, -6D1, -6D1A, -6K, -6K2, -80A, -80A2 CFM56-2, -2A, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B22, -7B22/B1, -7B24, -7B24/B1, -7B26, -7B26B1, -7B27, -7B27/B1, -7B27/B3, -7B22/B2, -7B26/B2
Bolt, Machine	J644P05B QQ	J644P05B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	-80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4 CFM56-3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26B1, -7B27, -7B27/2, -7B27/B1,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-7B27/B3, -7B22/B2, -7B26/B2
Bolt, Machine	J644P05D QQ	J644P05D	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -45A, -45A2, -80A1, -80A3 CF34-8C
				CFM International	CFM56-3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P06A QQ	J644P06A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A1, CF6-80A2, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2D1F, CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-3A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7 GE90-76B, GE90-77B, GE90-85B, GE90-90B,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4, CFM56- 5B4/2P,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B4/2P1, CFM56-5B4/3, CFM56-5B4/3B1, CFM56-5B4/P, CFM56-5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/P, CFM56-5C2/G4, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5C4/1, CFM56-5C4/P, CFM56- 5C4/1P, CFM56-7B18, CFM56-7B20, CFM56- 7B20/2, CFM56- 7B20/3, CFM56-7B22, CFM56- 7B22/2, CFM56- 7B22/3, CFM56- 7B22/3B1, CFM56- 7B22/B1, CFM56-7B22E, CFM56- 7B22E/B1, CFM56-7B24, CFM56- 7B24/2, CFM56- 7B24/3, CFM56- 7B24/3B1, CFM56- 7B24/B1, CFM56-7B24E, CFM56- 7B24E/B1, CFM56-7B26, CFM56- 7B26/2, CFM56- 7B26/3, CFM56- 7B26/3B1,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3, CFM56-7B27AE, CFM56-7B27E, CFM56-7B27E/B1,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B27E/B3, CFM56-7BE/F, CFM56-7B27E/B1F, CFM56-7B22/B2, CFM56-7B26/B2
Bolt, Machine	J644P06B QQ	J644P06B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50CA, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A8, CF6-80C2B1, CF6-80C2B2, CF6-80C2B4, CF6-80C2B6, CF6-80C2B1F, CF6-80C2B2F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-1A, CF34-3A, CF34-3A2, CF34-3A1, CF34-3B1, CF34-3B CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/3,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B2/P, CFM56-5B3/2P, CFM56-5B3/2P1, CFM56-5B3/3, CFM56-5B3/3B1, CFM56-5B3/P, CFM56-5B3/P1, CFM56-5B4, CFM56-5B4/2P, CFM56-5B4/2P1, CFM56-5B4/3, CFM56-5B4/3B1, CFM56-5B4/P, CFM56-5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/P, CFM56-5C2/G4, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P, CFM56-5C4/1P
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P07A QQ	J644P07A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A1, CF6-80A2, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4 CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7 GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	GE90-115B CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/P, CFM56- 5B3/2P, CFM56-5B3/P, CFM56-5B4, CFM56- 5B4/2P, CFM56-5B4/P, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56- 5B6/2P, CFM56-5B6/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56- 5C2/F4, CFM56-5C2/G,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5C2/G4, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C4, CFM56-5C4/1, CFM56-7B18, CFM56-7B20, CFM56-7B20/2, CFM56-7B20/3, CFM56-7B22, CFM56-7B22/2, CFM56-7B22/3, CFM56-7B22/3B1, CFM56-7B22/B1, CFM56-7B22/B2, CFM56-7B24, CFM56-7B24/2, CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24/B1, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/3,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26/B2, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3
Bolt, Machine	J644P07B QQ	J644P07B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50CA, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A8, CF6-80C2B1, CF6-80C2B2, CF6-80C2B4, CF6-80C2B6, CF6-80C2D1F, CF6-80C2B1F, CF6-80C2B2F, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7 GE90-110B1, GE90-113B, GE90-115B
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4, CFM56- 5B4/2P, CFM56- 5B4/2P1, CFM56-5B4/3, CFM56- 5B4/3B1, CFM56-5B4/P,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/P, CFM56-5C2/G4, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P, CFM56-5C4/1P, CFM56-7B18, CFM56-7B20,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B20/2, CFM56-7B20/3, CFM56-7B22, CFM56-7B22/2, CFM56-7B22/3, CFM56-7B22/3B1, CFM56-7B22/B1, CFM56-7B22E, CFM56-7B22E/B1, CFM56-7B24, CFM56-7B24/2, CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24/B1, CFM56-7B24E, CFM56-7B24E/B1, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/3, CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B26/B1, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3, CFM56-7B27AE, CFM56-7B27E, CFM56-7B27E/B1, CFM56-7B27E/B3, CFM56-7BE/F, CFM56-7B27E/B1F,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B22/B2, CFM56-7B26/B2
Bolt, Machine	J644P07D QQ	J644P07D	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A1, CF6-80A2, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6-80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80E1A2,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80E1A3, CF6-80E1A4
					CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7
				CFM International	CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/P,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B3/2P, CFM56-5B3/P, CFM56-5B4, CFM56-5B4/2P, CFM56-5B4/P, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/P, CFM56-5C2, CFM56-5C2/F, CFM56-5C3/F, CFM56-5C2/G, CFM56-5C3/G, CFM56-5C2/4, CFM56-5C2/F4, CFM56-5C2/G4, CFM56-5C3/F4, CFM56-5C3/G4, CFM56-5C4, CFM56-5C4/1, CFM56-7B20, CFM56-7B20/3, CFM56-7B22, CFM56-7B22/3, CFM56-7B22/3B1, CFM56-7B22/B1, CFM56-7B24, CFM56-7B24/3,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B24/3B1, CFM56-7B24/B1, CFM56-7B26, CFM56-7B26/3, CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26/B2, CFM56-7B27, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P08A QQ	J644P08A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50CA, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A8, CF6-80C2D1F, CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-3A1, CF34-3B1, CF34-3B, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1,
---------------	----------------	----------	---	---------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CF34-10E7 GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM56-2A, CFM56-2B, CFM56-2C, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56-5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2, CFM56-5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56-5B3/2P, CFM56-5B3/2P1, CFM56-5B3/3, CFM56-5B3/3B1, CFM56-5B3/P, CFM56-5B3/P1, CFM56-5B4, CFM56-5B4/2P, CFM56-5B4/2P1, CFM56-5B4/3, CFM56-5B4/3B1, CFM56-5B4/P, CFM56-5B4/P1, CFM56-5B5,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P, CFM56-5C2, CFM56-5C2/F, CFM56-5C3/F, CFM56-5C2/G, CFM56-5C2/P, CFM56-5C3/G, CFM56-5C2/4, CFM56-5C2/F4, CFM56-5C2/G4, CFM56-5C3/F4, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P, CFM56-5C4/1P, CFM56-7B18, CFM56-7B22/B2, CFM56-7B20, CFM56-7B20/2, CFM56-7B20/3, CFM56-7B22, CFM56-7B22/2, CFM56-7B22/3, CFM56- 7B22/3B1, CFM56-7B22/B1, CFM56-7B22E, CFM56- 7B22E/B1, CFM56-7B24, CFM56-7B24/2, CFM56-7B24/3,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B24/3B1, CFM56-7B24/B1, CFM56-7B24E, CFM56-7B24E/B1, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/3, CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26/B2, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3, CFM56-7B27AE, CFM56-7B27E, CFM56-7B27E/B1, CFM56-7B27E/B3, CFM56-7B27E/F
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26/B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P08D QQ	J644P08D	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6, -6D, -6D1, -6D1A, -6K, -6K2, -50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3, -80E1A2, -80E1A3, -80E1A4 CF34-8C



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

				CFM International	CFM56-2B, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P08E QQ	J644P08E	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P09A QQ	J644P09A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A1, CF6-80A2, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F,
---------------	----------------	----------	---	---------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CF6-80E1A2, CF6-80E1A3, CF6-80E1A4 CF34-3A1, CF34-3B, CF34-3B1, CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7, GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM International CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5-A1/F,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56-5B1/P, CFM56- 5B1/2P, CFM56-5B2, CFM56-5B1/3, CFM56-5B2/3, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B2/P, CFM56- 5B2/2P, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4/3 CFM56- 5B4/3B1, CFM56-5B5/3, CFM56-5B6/3, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B4, CFM56-5B4/P, CFM56- 5B4/P1, CFM56- 5B4/2P, CFM56- 5B4/2P1, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/P,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B6/2P, CFM56-5B7, CFM56-5B7/P, CFM56-5B8/P, CFM56-5B9/P, CFM56-5B7/3, CFM56-5B8/3, CFM56-5B9/3, CFM56-5B9/2P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/G4, CFM56-5C2/P, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/P, CFM56-5C4/1, CFM56-5C4/1P, CFM56-7B18, CFM56-7B20, CFM56-7B20/2, CFM56-7B20/3, CFM56-7B22, CFM56-7B22/2,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B22/B1, CFM56-7B22/3, CFM56-7B22/3B1, CFM56-7B22E, CFM56-7B22E/B1, CFM56-7B24, CFM56-7B24/2, CFM56-7B24/B1, CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24E, CFM56-7B24E/B1, CFM56-7B26/3, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/B1, CFM56-7B26/3B1, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B2, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27A, CFM56-7B27AE, CFM56-7B27/3, CFM56-7B27/3F, CFM56-7B26/3B2, CFM56-7B27/B1, CMF56-7B27/B3, CFM56-7B27/2, CFM56-7B27/3B1, CFM56-7B27/3B3, CFM56-7B27A/3, CFM56-7B27E/B1, CFM56-7B27/3B1F, CFM56-7B27E/B3, CFM56-7B27E, CFM56-7B27E/F, CFM56-7B27E/B1F
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					-5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26/B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P09C QQ	J644P09C	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A, -80A2 CFM56-B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P
Bolt, Machine	J644P09D QQ	J644P09D	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50CA, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A8, CF6-80C2B1, CF6-80C2B2, CF6-80C2B4, CF6-80C2B6, CF6-80C2D1F, CF6-80C2B1F, CF6-80C2B2F, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-8C CFM56-2A, CFM56-2B, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4, CFM56- 5B4/2P, CFM56- 5B4/2P1,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-5B4/3, CFM56-5B4/3B1, CFM56-5B4/P, CFM56-5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P
Bolt, Machine	J644P09E QQ	J644P09E	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B2,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

				CFM International	-80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B5FA, -80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4 CFM56-B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P
Bolt, Machine	J644P10A QQ	J644P10A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4 CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, CF34-3B1, CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6, CF34-8E6A1,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7, GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/P, CFM56- 5B3/2P, CFM56-5B3/P, CFM56-5B4, CFM56- 5B4/2P,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B4/P, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56- 5B6/2P, CFM56-5B6/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56- 5C2/F4, CFM56-5C2/G, CFM56- 5C2/G4, CFM56-5C3/F, CFM56- 5C3/F4, CFM56-5C3/G, CFM56- 5C3/G4, CFM56-5C4, CFM56-5C4/1, CFM56-7B18, CFM56-7B20, CFM56- 7B20/2, CFM56- 7B20/3, CFM56-7B22, CFM56- 7B22/2, CFM56- 7B22/3, CFM56- 7B22/3B1, CFM56- 7B22/B1, CFM56- 7B22/B2, CFM56-7B24,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B24/2, CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24/B1, CFM56-7B26/2, CFM56-7B26/3, CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26/B2, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B27A, CFM56-7B27A/3
Bolt, Machine	J644P10B QQ	J644P10B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4
				CFM International	CF34-1A, -3A, -3A1, -3A2, -3B, -3B1 CFM56-2B, -5, -5A1/F, -5A3, -5A4, -5A4/F, 5A5, -5A5/F



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P11A QQ	J644P11A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6 -50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F,
---------------	----------------	----------	---	---------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80E1A2, CF6-80E1A3, CF6-80E1A4
					CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, CF34-3B1, CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7
					GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B
				CFM International	CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5-A1/F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56-5B1/P, CFM56- 5B1/2P, CFM56-5B2, CFM56-5B1/3, CFM56-5B2/3, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B2/P, CFM56- 5B2/2P, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4/3 CFM56- 5B4/3B1, CFM56-5B5/3, CFM56-5B6/3, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B4, CFM56-5B4/P, CFM56- 5B4/P1, CFM56- 5B4/2P, CFM56- 5B4/2P1, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/P,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B6/2P, CFM56-5B7, CFM56-5B7/P, CFM56-5B8/P, CFM56-5B9/P, CFM56-5B7/3, CFM56-5B8/3, CFM56-5B9/3, CFM56-5B9/2P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/G4, CFM56-5C2/P, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/P, CFM56-5C4/1, CFM56-5C4/1P, CFM56-7B18, CFM56-7B20, CFM56-7B20/2, CFM56-7B20/3, CFM56-7B22, CFM56-7B22/2,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B22/B1, CFM56-7B22/3 CFM56-7B22/3B1, CFM56-7B22E, CFM56-7B22E/B1, CFM56-7B24, CFM56-7B24/2, CFM56-7B24/B1, CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24E, CFM56-7B24E/B1, CFM56-7B26/3, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/B1, CFM56-7B26/3B1, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B2, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B26E/F, CFM56-7B27, CFM56-7B27A, CFM56-7B27AE, CFM56-7B27/3, CFM56-7B27/3F, CFM56-7B26/3B2, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27/2, CFM56-7B27/3B1, CFM56-7B27/3B3, CFM56-7B27A/3, CFM56-7B27E/B1, CFM56-7B27/3B1F, CFM56-7B27E/B3, CFM56-7B27E, CFM56-7B27E/F, CFM56-7B27E/B1F
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P11D QQ	J644P11D	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A1, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA, -80C2B7F, -80C2D1F, -80E1A2, -80E1A4, -80E1A3
Bolt, Machine	J644P12A QQ	J644P12A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -45A, -45A2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -80A, -80A2, -80A1, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B1F, -80C2B2, -80C2B2F, -80C2B4, -80C2B4F, -80C2B5F, -80C2B6, -80C2B6F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	-80C2B6FA, -80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4 CF34-1A, -3A, -3A1, -3A2, -3B -3B1, -8C GE90-76B CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20,
--	--	--	--	----------------------	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P12B QQ	J644P12B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4 CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6, CF34-8E6A1 GE90-76B, GE90-77B, GE90-85B, GE90-90B CFM International	CFM56-3, CFM56-3B, CFM56-3C, CFM56-5,
--	--	--	--	--	---	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/P, CFM56- 5B3/2P, CFM56-5B3/P, CFM56-5B4, CFM56- 5B4/2P, CFM56-5B4/P, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56- 5B6/2P, CFM56-5B6/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56- 5C2/F4, CFM56-5C2/G, CFM56- 5C2/G4, CFM56-5C3/F, CFM56- 5C3/F4, CFM56-5C3/G, CFM56- 5C3/G4, CFM56-5C4,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P12C QQ	J644P12C	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CFM56-5C4/1 CF6-6D, -6D1, -6D1A, -6K, -6K2 CFM56-5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P12D QQ	J644P12D	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-6D, -6D1, -6D1A, -6K, -6K2, -80E1A2, -80E1A3, -80E1A4 CFM56-2B



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P12E QQ	J644P12E	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2 CFM56-B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P
Bolt, Machine	J644P13A QQ	J644P13A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50CA, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A8, CF6-80C2B1,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80C2B2, CF6-80C2B4, CF6-80C2B6, CF6-80C2D1F, CF6-80C2B1F, CF6-80C2B2F, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-1A, CF34-3A, CF34-3A2, CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7 GE90-76B,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B4/2P, CFM56-5B4/2P1, CFM56-5B4/3, CFM56-5B4/3B1, CFM56-5B4/P, CFM56-5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P, CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56-5C2/F4, CFM56-5C2/G, CFM56-5C2/P, CFM56-5C2/G4, CFM56-5C3/F, CFM56-5C3/F4, CFM56-5C3/G, CFM56-5C3/G4,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P, CFM56- 5C4/1P, CFM56-7B18, CFM56-7B20, CFM56- 7B20/2, CFM56- 7B20/3, CFM56-7B22, CFM56- 7B22/2, CFM56- 7B22/3, CFM56- 7B22/3B1, CFM56- 7B22/B1, CFM56-7B22E, CFM56- 7B22E/B1, CFM56-7B24, CFM56- 7B24/2, CFM56- 7B24/3, CFM56- 7B24/3B1, CFM56- 7B24/B1, CFM56-7B24E, CFM56- 7B24E/B1, CFM56-7B26, CFM56- 7B26/2, CFM56- 7B26/3,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3, CFM56-7B27AE, CFM56-7B27E,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B27E/B1, CFM56-7B27E/B3, CFM56-7BE/F, CFM56-7B27E/B1F, CFM56-7B22/B2, CFM56-7B26/B2
Bolt, Machine	J644P13B QQ	J644P13B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6 GE90-76B CFM International CFM56-2A
Bolt, Machine	J644P14A QQ	J644P14A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, -45A2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	-80C2A5, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6 CF34-1A, -3A, -3A2 GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26/B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P14B QQ	J644P14B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	-80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4 CFM56-2, 2A, -2B, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P14D QQ	J644P14D	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80C2B1F, -80C2B2F, -80C2B4F, -80C2B6F CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P15A QQ	J644P15A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-45A, CF6-45A2, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50CA, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4 CF6-80E1A4/B CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5B1, CF34-8C5A2, CF34-8C5A3,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6, CF34-8E6A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7 GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM International CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56-5B1/P, CFM56- 5B1/2P, CFM56-5B2, CFM56-5B1/3, CFM56-5B2/3,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B2/P, CFM56- 5B2/2P, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4/3, CFM56- 5B4/3B1, CFM56-5B5/3, CFM56-5B6/3, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B4, CFM56-5B4/P, CFM56- 5B4/P1, CFM56- 5B4/2P, CFM56- 5B4/2P1, CFM56-5B5, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/P, CFM56- 5B6/2P, CFM56-5B7, CFM56-5B7/P, CFM56-5B8/P, CFM56-5B9/P, CFM56-5B7/3, CFM56-5B8/3, CFM56-5B9/3, CFM56- 5B9/2P, CFM56-5C2,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5C2/4, CFM56-5C2/F, CFM56- 5C2/F4, CFM56-5C2/G, CFM56- 5C2/G4, CFM56-5C2/P, CFM56-5C3/F, CFM56- 5C3/F4, CFM56-5C3/G, CFM56- 5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/P, CFM56-5C4/1, CFM56- 5C4/1P, CFM56-7B18, CFM56-7B20, CFM56- 7B20/2, CFM56- 7B20/3, CFM56-7B20E, CFM56-7B22, CFM56- 7B22/2, CFM56- 7B22/B1, CFM56- 7B22/B2 CFM56- 7B22/3, CFM56- 7B22/3B1, CFM56-7B22E, CFM56- 7B22E/B1, CFM56-7B24,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B24/2, CFM56-7B24/B1, CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24E, CFM56-7B24E/B1, CFM56-7B26/3, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/B1, CFM56-7B26/3B1, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B2, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27A, CFM56-7B27AE, CFM56-7B27/3,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B27/3F, CFM56-7B26/3B2, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27/2, CFM56-7B27/3B1, CFM56-7B27/3B3, CFM56-7B27A/3, CFM56-7B27E/B1, CFM56-7B27/3B1F, CFM56-7B27E/B3, CFM56-7B27E/B3, CFM56-7B27E/F, CFM56-7B27E/B1F
Bolt, Machine	J644P15B QQ	J644P15B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -45A, -45A2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -80A, -80A2, -80A1, -80A3, -80C2A1, -80C2A2,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

				CFM International	-80C2A3, -80C2A5, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6 CFM56-2, -2A, -2B, -3, -3B, -3C
Bolt, Machine	J644P16A QQ	J644P16A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, CF6-6D1, CF6-6D1A, CF6-6K, CF6-6K2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A8, CF6-80C2B1, CF6-80C2B2, CF6-80C2B4, CF6-80C2B6, CF6-80C2D1F, CF6-80C2B1F, CF6-80C2B2F, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6F, CF6- 80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2A5F, CF6-80E1A2, CF6-80E1A3,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CF6-80E1A4, CF6-80E1A4/B
					CF34-1A, CF34-3A, CF34-3A2, CF34-3A1, CF34-3B1, CF34-3B, CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1
					GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B
				CFM International	CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B1/P, CFM56-5B2, CFM56- 5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56- 5B3/2P, CFM56- 5B3/2P1, CFM56-5B3/3, CFM56- 5B3/3B1, CFM56-5B3/P, CFM56- 5B3/P1, CFM56-5B4, CFM56- 5B4/2P, CFM56- 5B4/2P1, CFM56-5B4/3, CFM56- 5B4/3B1, CFM56-5B4/P, CFM56- 5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56- 5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56- 5B9/2P,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B9/3, CFM56-5B9/P, CFM56-7B18, CFM56-7B20, CFM56- 7B20/2, CFM56- 7B20/3, CFM56-7B22, CFM56- 7B22/2, CFM56- 7B22/3, CFM56- 7B22/3B1, CFM56- 7B22/B1, CFM56-7B22E, CFM56- 7B22E/B1, CFM56-7B24, CFM56- 7B24/2, CFM56- 7B24/3, CFM56- 7B24/3B1, CFM56- 7B24/B1, CFM56-7B24E, CFM56- 7B24E/B1, CFM56-7B26, CFM56- 7B26/2, CFM56- 7B26/3, CFM56- 7B26/3B1, CFM56- 7B26/3B2,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F, CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3, CFM56-7B27AE, CFM56-7B27E, CFM56-7B27E/B1, CFM56-7B27E/B3,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7BE/F, CFM56-7B27E/B1F, CFM56-7B22/B2, CFM56-7B26/B2
Bolt, Machine	J644P16B QQ	J644P16B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -802B6FA, -80C2B7F, -80C2A5F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P16F QQ	J644P16F	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4
Bolt, Machine	J644P17A QQ	J644P17A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-45A, CF6-45A2, CF6-50CA, CF6-50C, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50C2-F, CF6-50C2-R, CF6-50E, CF6-50E1, CF6-50E2, CF6-80A, CF6-80A2, CF6-80A1, CF6-80A3, CF6-80C2D1F, CF6-80C2B1F, CF6-80C2B2F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CF6-80C2B4F, CF6-80C2B6F, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, CF6-80E1A4/B CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7 GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B, GE90-115B CFM International CFM56-2, CFM56-2A, CFM56-2B, CFM56-3, CFM56-3B, CFM56-3C, CFM56-5, CFM56-5A1/F, CFM56-5A3, CFM56-5A4, CFM56-5A4/F, CFM56-5A5, CFM56-5A5/F, CFM56-5B1, CFM56- 5B1/2P, CFM56-5B1/3, CFM56-5B1/P, CFM56-5B2,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5B2/2P, CFM56-5B2/3, CFM56-5B2/P, CFM56-5B3/2P, CFM56-5B3/2P1, CFM56-5B3/3, CFM56-5B3/3B1, CFM56-5B3/P, CFM56-5B3/P1, CFM56-5B4, CFM56-5B4/2P, CFM56-5B4/2P1, CFM56-5B4/3, CFM56-5B4/3B1, CFM56-5B4/P, CFM56-5B4/P1, CFM56-5B5, CFM56-5B5/3, CFM56-5B5/P, CFM56-5B6, CFM56-5B6/2P, CFM56-5B6/3, CFM56-5B6/P, CFM56-5B7, CFM56-5B7/3, CFM56-5B7/P, CFM56-5B8/3, CFM56-5B8/P, CFM56-5B9/2P, CFM56-5B9/3, CFM56-5B9/P,
--	--	--	--	--	---



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-5C2, CFM56-5C2/4, CFM56-5C2/F, CFM56- 5C2/F4, CFM56-5C2/G, CFM56-5C2/P, CFM56- 5C2/G4, CFM56-5C3/F, CFM56- 5C3/F4, CFM56-5C3/G, CFM56- 5C3/G4, CFM56-5C3/P, CFM56-5C4, CFM56-5C4/1, CFM56-5C4/P, CFM56- 5C4/1P, CFM56-7B18, CFM56-7B20, CFM56- 7B20/2, CFM56- 7B20/3, CFM56-7B22, CFM56- 7B22/2, CFM56- 7B22/3, CFM56- 7B22/3B1, CFM56- 7B22/B1, CFM56-7B22E, CFM56- 7B22E/B1, CFM56-7B24, CFM56- 7B24/2,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					CFM56-7B24/3, CFM56-7B24/3B1, CFM56-7B24/B1, CFM56-7B24E, CFM56-7B24E/B1, CFM56-7B26, CFM56-7B26/2, CFM56-7B26/3, CFM56-7B26/3B1, CFM56-7B26/3B2, CFM56-7B26/3B2F, CFM56-7B26/3F, CFM56-7B26/B1, CFM56-7B26E, CFM56-7B26E/B1, CFM56-7B26E/B2, CFM56-7B26E/B2F, CFM56-7B26E/F, CFM56-7B27, CFM56-7B27/2, CFM56-7B27/3, CFM56-7B27/3B1, CFM56-7B27/3B1F,
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					CFM56-7B27/3B3, CFM56-7B27/3F, CFM56-7B27/B1, CFM56-7B27/B3, CFM56-7B27A, CFM56-7B27A/3, CFM56-7B27AE, CFM56-7B27E, CFM56-7B27E/B1, CFM56-7B27E/B3, CFM56-7BE/F, CFM56-7B27E/B1F, CFM56-7B22/B2, CFM56-7B26/B2
Bolt, Machine	J644P17B QQ	J644P17B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A8, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2D1F, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F, -80C2A5F
Bolt, Machine	J644P17D QQ	J644P17D	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A, -80A1, -80A2, -80A3 CFM56-5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F
Bolt, Machine	J644P18A QQ	J644P18A	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-45A, -45A2, -50C, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50CA, -50E, -50E1, -50E2, -80A, -80A1, -80A2, -80A3, -80C2D1F, -80C2A5F CF34-1A, -3A, -3A1, -3A2, -3B, -3B1 CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P18E QQ	J644P18E	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

					-5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26/B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
--	--	--	--	--	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P19F QQ	J644P19F	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A, -80A2 CFM56-5B1, -5B1/2P, -5B2, -5B2/2P, -5B3/2P, -5B4, -5B4/2P, -5B5, -5B6, -5B6/2P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1
Bolt, Machine	J644P20A QQ	J644P20A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A8, -80C2A5F, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B5F, -80C2B6F, -80C2B6FA, -80B2B7F, -80C2B8F, -80C2D1F



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CF34-8C CFM56-2, -2A, -2B, 3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P20B QQ	J644P20B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	-7B26/B2 CF6-80A, -80A1, -80A2, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A8, -80C2A5F, -80C2B1, -80C2B2, -80C2B4, -80C2B6, -80C2B1F, -80C2B2F, -80C2B4F, -80C2B6F, -80C2D1F
Bolt, Machine	J644P20C QQ	J644P20C	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2
Bolt, Machine	J644P21A QQ	J644P21A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-6D, -6D1, -6D1A, -6K, -6K2, -50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	CF34-8C GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-7B26B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P21B QQ	J644P21B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A1, -80A3 CFM56-3, -3B1, -3B2, -3C1
Bolt, Machine	J644P22A QQ	J644P22A	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A1, -80A3 CFM56-2, -2A, -2B, -3, -3B, -3C
Bolt, Machine	J644P23A QQ	J644P23A	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A1, -80A3, -80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B1F, -80C2B2, -80C2B2F, -80C2B4, -80C2B4F, -80C2B5F, -80C2B6, -80C2B6F, -80C2B6FA,



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033

PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

				CFM International	-80C2B7F, -80C2B8F, -80C2D1F, -80E1A2, -80E1A3, -80E1A4 CF34-1A, -3A, -3A1, -3A2, -3B, -3B1 GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B1/2P, -5B1/P, -5B2, -5B2/2P, -5B2/P, -5B3/2P, -5B3/P, -5B4, -5B4/2P, -5B4/P, -5B5, -5B5/P, -5B6, -5B6/2P, -5B6/P, -5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4,
--	--	--	--	----------------------	--



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P23B QQ	J644P23B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3
Bolt, Machine	J644P25A QQ	J644P25A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3
Bolt, Machine	J644P25B QQ	J644P25B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A2



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

					-5B5/P, -5B6, -5B6/2P, -5B6/P, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B22/B1, -7B24, -7B24/2, -7B24/B1, -7B26, -7B26/2, -7B26/B1, -7B27, -7B27/2, -7B27/B1, -7B27/B3, -7B27A, -7B22/B2, -7B26/B2
Bolt, Machine	J644P28B QQ	J644P28B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2-F, -50C2-R, -50E, -50E1, -50E2, -45A, -45A2, -80A, -80A1, -80A2, -80A3
Bolt, Machine	J644P30B QQ	J644P30B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3
Bolt, Machine	J644P31B QQ	J644P31B	Identity per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A2



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033

PMA NO. PQ0816NE
 SUPPLEMENT NO. 245 Amdmt 10
 DATE: November 9, 2015

Bolt, Machine	J644P33A QQ	J644P33A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric CFM International	CF6-80A, -80A2 CFM56 -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P
Bolt, Machine	J644P33B QQ	J644P33B	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A2
Bolt, Machine	J644P37A QQ	J644P37A	Identicality per 14 CFR 21.303. <u>DWG No.:</u> 107 <u>Rev:</u> D <u>Date:</u> 01/05/01 or later FAA-approved revisions.	General Electric	CF6-80A, -80A1, -80A2, -80A3

------(END OF DATA)-----



FAA

Manufacturing Inspection District Office, ANE-MIDO-41

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Turbine Kinetics, Inc.
A HEICO Aerospace Company
60 Sequin Drive
Glastonbury, CT 06033


PMA NO. PQ0816NE
SUPPLEMENT NO. 245 Amdmt 10
DATE: November 9, 2015

GENERAL NOTES:

Provide minor design changes in a manner as determined by the ACO. Process major design changes to drawings and specifications in the same manner as that for an original FAA-PMA

The FAA accepted the ICA approach for the above articles with their designs. The ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements for supplemental ICA readily available per 14 CFR 21.50.


Thomas Boudreau, Manager,
Engine Certification Office


Richard P. Warren, Manager
Bradley Manufacturing Inspection
District Office