

## AW139 Engine Exhaust Duct

### Manufacturer:



### Model:

AW139 Helicopter

### Part #:

3G7800L00132	3G7800L00232
3G7800L00134	3G7800L00234
3G7806P01531	3G7806P01631
3G7806P01532	3G7806P01632

### Repair Work Scope:

- Full FPI, dimensional, and visual inspection
- Full thermal blanket replacement (not patch repair)
- Flat seal and anchor nut replacement
- Gas tungsten arc (TIG) and resistance spot weld repair
- Replacement of support bracket
- Repair performed in accordance with B.T. 139-221 approved technical data

### About ATI

Aircraft Technology, Inc., (ATI), a subsidiary of HEICO Corporation, is a FAA/EASA Part 145 Repair Station. Centrally located in Hollywood, FL, ATI supports a wide range of rotary and fixed wing components found on both commercial and military platforms around the world.

By utilizing lean principles and inventory exchanges, ATI is able to offer a rapid, and competitive, turnaround for all your repair services.

Authorized Service Center MRO Support for North, Central, & South America  
Service Center MRO Location: Hollywood, Florida U.S.A.



### After



## Repair Benefits

- ▶ Approved Supplier to AgustaWestland
- ▶ Extended Repair Life
- ▶ Repair Expertise
- ▶ OEM Technical Support
- ▶ Lower Support Bracket Manufacture Capability
- ▶ Higher Grade of Blanket Material
- ▶ Cost Savings Over Replacement
- ▶ Immediate Exchange Availability
- ▶ In-house "Fit and Function" Inspection Tooling
- ▶ FAA-DER Approved Repair