

HEICO

LID ASSY

Seal Dynamics Part Number: 841-00-302-31SD, 841-00-302-32SD

Recaro Aircraft Seating Inc. Part Number: 841-00-302-31, 841-00-302-32

Next Higher Assembly Part Number: 841-00-300-31, 841-00-300-32: Armcap Assembly

Eligibility:

[See FAA PMA Supplement](#)

IPC Reference:



B777-25-20

Quantity:

1 per unit



Illustration not Available for 841-00-302-32SD



Location:

Armrest Ainstl.