

FEDERAL AVIATION ADMINISTRATION-PARTS MANUFACTURER APPROVAL


Aero Design, Inc.
 A HEICO Aerospace Company
 385 Industrial Drive
 Mt. Juliet, Tennessee 37122

PMA NO. PQ1465CE
 SUPPLEMENT NO. 182
 DATE: July 30, 2008


<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement for Part Number</u>	<u>Approval Basis and Approved Design Data</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Terminal Connector	AD-9357-001	Saft 009357-001 Installed in Saft Batteries 43B034LB03, 34LB03, and 021904-000 Installed in GE Battery 43B034LB03	Test and Computation per 14 CFR § 21.303 (c)(4) <u>Dwg No:</u> AD-9357-001, <u>Rev:</u> 0, <u>Date:</u> 5/5/08, or later FAA-approved revisions	McDonnell Douglas	DC-9 Series All (-11 through -87), MD-88
Terminal Connector	AD-9357-003	Saft 009357-003 Installed in Saft Batteries 43B034LB03, 34LB03, and 021904-000 Installed in GE Battery 43B034LB03	Test and Computation per 14 CFR § 21.303 (c)(4) <u>Dwg No:</u> AD-9357-003, <u>Rev:</u> 0, <u>Date:</u> 5/5/08, or later FAA-approved revisions	McDonnell Douglas	DC-9 Series All (-11 through -87), MD-88

-END OF LISTING-

NOTE: Provide minor design changes in a manner as determined by the ACO. Handle major design changes to drawings and specifications in the same manner as that for an original FAA-PMA. If TC holder's ICA applies to these replacement parts, provide a statement noting such. If not, provide supplementary ICA per 14 CFR §21.50.



 Melvin D. Taylor, Manager Atlanta
 Aircraft Certification Office



 For: Jim Reeves, Manager Atlanta
 Manufacturing Inspection District Office