

PARTS MANUFACTURER APPROVAL NO: PQ2710CE
 PRODUCTION APPROVAL LISTING - SUPPLEMENT NO. 27
 DATE: February 7, 2008

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Flight Specialties Components Corporation
 A HEICO Subsidiary
 375 Alpha Park
 Highland Heights, OH 44143

<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement For</u>	<u>FAA Approval Basis and Approved Design Data</u>	<u>Installation Eligibility: MAKE</u>	<u>Installation Eligibility: MODEL</u>
Ring, Sealing	44066FS	Eaton P/N 44066 installed in Eaton Chip Detector P/N VB3503	Test and Computations per 14 CFR § 21.303 DWG No.: 44066FS Rev.: A Date: 4/17/2006 or later FAA approved revisions	Boeing Rolls Royce	747-400 Series, 767-300 Series RB211-524G2-19 RB211-524G3-19 RB211-524H-36
Ring, Sealing	44066FS	Eaton P/N 44066 installed in Eaton Chip Detector P/N 1B7802	Test and Computations per 14 CFR § 21.303 DWG No.: 44066FS Rev.: A Date: 4/17/2006 or later FAA approved revisions	Boeing Airbus Rolls Royce	777-200 Series, A340-541, A340-642 RB211 TRENT 553-61 RB211 TRENT 553A2-61 RB211 TRENT 556-61 RB211 TRENT 556A2-61 RB211 TRENT 556B-61 RB211 TRENT 556B2-61 RB211 TRENT 560-61 RB211 TRENT 560A2-61 RB211 TRENT 875-17 RB211 TRENT 877-17 RB211 TRENT 884-17 RB211 TRENT 884B-17 RB211 TRENT 892-17 RB211 TRENT 892B-17 RB211 TRENT 895-17
Touch Screen	1302151-005FS	Rockwell Collins P/N 1302151-005 installed in Rockwell Collins LCD Monitor P/Ns: 1302045-100, 1302046-100	Test and Computations per 14 CFR § 21.303 DWG No:1302151-005FS Rev: A Date: 08/03/2007 or later FAA-approved revisions	Boeing	747-400 Series (w/STC ST00720LA installed)

-----End of Listing-----

Kimberly S. Edwards

for Matthew E. Tomsheck
 Manager, Manufacturing
 Inspection District Office

PARTS MANUFACTURER APPROVAL NO: PQ2710CE
PRODUCTION APPROVAL LISTING - SUPPLEMENT NO. 28

DATE: March 11, 2008

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Flight Specialties Components Corporation
A HEICO Subsidiary
375 Alpha Park
Highland Heights, OH 44143

<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement For</u>	<u>FAA Approval Basis and Approved Design Data</u>	<u>Installation Eligibility: MAKE</u>	<u>Installation Eligibility: MODEL</u>
Shaft, Motor	FS519882-2	Honeywell P/N 519882-2 installed in Honeywell Pneumatic Drive Actuator PNs: 126344-1-1, 126344-3-1, 126344-5-1, 126344-7-1, 126344-9-1, 126344-13-1, 126748-1, 126748-3, 126748-5, 126748-7	Test and Computations per 14 CFR § 21.303 DWG No: FS519882 Rev: C Date: 11/15/2007 or later FAA-approved revisions	Boeing	747-400 Series
Screen, Touch	1302151-005FS	Rockwell Collins P/N 1302151-005 installed in Rockwell LCD Monitor PNs: 1302045-100, 1302046-100	Test and Computations per 14 CFR § 21.303 DWG No: 1302151-005FS Rev: A Date: 08/03/2007 or later FAA-approved revisions	Boeing	767-300 Series With STC ST01665LA installed
Screen, Touch	1302151-005FS	Rockwell Collins P/N 1302151-005 installed in B/E Aerospace Seat Assembly P/Ns: 87850001, 87850002, 87850003, 87850004, 87850005, 87850006, 87850011, 87850015, 87850016, 87850017, 87850018, 87850101, 87850102, 87850103	Test and Computations per 14 CFR § 21.303 DWG No: 1302151-005FS Rev: A Date: 08/03/2007 or later FAA-approved revisions	Boeing	777-200 Series

-----End of Listing-----

for Kimberly S. Edwards
Matthew E. Tomsheck
Manager, Manufacturing
Inspection District Office