

FAA – PARTS MANUFACTURER APPROVAL (PMA) SUPPLEMENT


Seal Dynamics  
 A HEICO Aerospace Company  
 13780 McCormick Drive  
 Tampa, Florida 33626

**PMA NO.:** PQ1715CE  
**SUPPLEMENT No.:** ODA-SD-025  
**DATE:** March 11, 2014

<u>Article Name</u>	<u>Part Number</u>	<u>Replacement For</u>	<u>Approval Basis and Approved Design Data</u>	<u>Eligibility (Make)</u>	<u>Eligibility (Model)</u>
Lid Assy	841-00-302-31SD	Recaro Aircraft Seating P/N: 841-00-302-31	Tests and Computations per 14 CFR § 21.303, Dwg No.: 841-00-302-3XSD, Rev.: IR, Dated: 8/2/13, or later FAA approved revisions.	Boeing	777-300 Series
Lid Assy	841-00-302-32SD	Recaro Aircraft Seating P/N: 841-00-302-32	Tests and Computations per 14 CFR § 21.303, Dwg No.: 841-00-302-3XSD, Rev.: IR, Dated: 8/2/13, or later FAA approved revisions.	Boeing	777-300 Series

----- End of Listing -----

NOTE: Minor design changes (reference 14 CFR part 21 §§ 21.93 and 21.95) and major design changes (reference 14 CFR part 21 §§ 21.93 and 21.97) to drawings and specifications must be accomplished in accordance with the FAA approved HEICO PMA ODA Procedures Manual.



\_\_\_\_\_  
 Marco Cuberos  
 PMA ODA administrator  
 HEICO Aerospace Corporation

This Supplement is an attachment to FAA-PMA approval letter dated August 28, 2003