

FEDERAL AVIATION ADMINISTRATION-PARTS MANUFACTURER APPROVAL

Seal Dynamics
13780 McCormick Drive
Tampa, FL 33626


PMA NO. PQ1715CE
SUPPLEMENT NO. 93
DATE: February 7, 2007

<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement For Part Number</u>	<u>Approved Basis and Approved Design Data</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Support	145-36830-001SD	Embraer P/N 145-36830-001	Test and Computations per 14 CFR § 21.303, <u>DWG NO:</u> 145-36830-001SD <u>REV:</u> IR <u>DATE:</u> 11/17/06 or later FAA Approved revisions	Embraer	EMB-135 Series EMB-145 Series
Shaft Assy	145-42870-405SD	Embraer P/N 145-42870-405	Test and Computations per 14 CFR § 21.303, <u>DWG NO:</u> 145-42870-405SD <u>REV:</u> IR <u>DATE:</u> 11/27/06 or later FAA Approved revisions	Embraer	EMB-135 Series EMB-145 Series

-----END OF LISTING-----

NOTE: Provide minor design changes in a manner as determined by the ACO. Handle major design changes to drawings and specifications in the same manner as that for an original FAA-PMA. If TC holder's ICA applies to these replacement parts, provide a statement noting such. If not, provide supplementary ICA per 14 CFR § 21.50.


for Melvin D. Taylor, Manager Atlanta
Aircraft Certification Office


Mack Riley, Manager Orlando
Manufacturing Inspection District Office