

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL


Turbine Kinetics, Inc.
 A HEICO Aerospace Company
 60 Sequin Drive
 Glastonbury, CT 06033


PMA NO. PQ0816NE
 SUPPLEMENT NO. 398
 DATE May 19, 2004

| Part Name | Part Number | Approved Replacement for Part Number | Approval Basis and Approved Design Data | Make Eligibility | Model Eligibility |
|---------------------|--------------|--------------------------------------|---|-------------------|---|
| Arm, Vane Actuation | KT1834M58G01 | 1834M58G01 | Test and Computations per 14 CFR § 21.303 <u>DWG No:</u> KT1834M58 <u>Rev:</u> None <u>Date:</u> 02/06/04 or later FAA approved revisions | CFM International | CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B2, -5B4, -5B5, -5B6, -5B7, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B7/P, -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P, -5C2, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C2/4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1 |
| Arm, Vane Actuation | KT1834M58G02 | 1834M58G02 | Test and Computations per 14 CFR § 21.303 <u>DWG No:</u> KT1834M58 <u>Rev:</u> None <u>Date:</u> 02/06/04 or later FAA approved revisions | CFM International | CFM56-2, -2A, -2B, -3, -3B, -3C, -5, -5A1/F, -5A3, -5A4, -5A4/F, -5A5, -5A5/F, -5B1, -5B2, -5B4, -5B5, -5B6, -5B7, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B7/P, -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P, -5C2, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C2/4, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C4, -5C4/1, -7B18, -7B20, -7B20/2, -7B22, -7B22/2, -7B24, -7B24/2, -7B26, -7B26/2, -7B27, -7B27/2 |

----- (END OF LISTING) -----

NOTE: Minor design changes (reference 14 CFR part 21 §§ 21.93 and 21.95) must be submitted in a manner as determined by the ACO. Major design changes (reference 14 CFR part 21 §§ 21.93 and 21.97) to drawings and specifications are to be handled in the same manner as that for an original FAA-PMA.


 Wego Wang
 Aerospace Engineer
 Engine Certification Office


 Earl S. Seabrooks
 Manager, Manufacturing Inspection
 District Office, NE-MIDO-41